


석면비산측정 결과보고서

- 지도초교선치분교장 교사 지정폐기물 철거공사 -

[별첨1] 측정 위치도(측정 장소)

2014. 5. 27.



편 례	*NO				
	시료채취	부지경계선	위생설비	음압설비	대상건축물



<p>번호</p>	<p>*NO</p>				
	<p>시료채취</p>	<p>부지경계선</p>	<p>위생설비</p>	<p>폐기물반출구</p>	<p>대상건축물</p>

[별첨2] 측정 결과

2014. 05. 27.					
측정위치		측정시간(분)	유량(l/min)	측정농도 [기준: 0.01개/cm ³]	초과 여부
*1	부지경계선1	9:00 ~ 13:10	9.93	불검출 [검출한계 0.002미만]	미만
*2	부지경계선2	9:02 ~ 13:12	9.92	불검출 [검출한계 0.002미만]	미만
*3	부지경계선3	9:03 ~ 13:13	9.94	불검출 [검출한계 0.002미만]	미만
*4	부지경계선4	9:04 ~ 13:14	9.9	불검출 [검출한계 0.002미만]	미만
*5	작업장주변	9:10 ~ 11:20	9.89	불검출 [검출한계 0.002미만]	미만
*6	위생설비입구	9:15 ~ 10:00	9.87	불검출 [검출한계 0.002미만]	미만
*7	음압기배출구	9:17 ~ 10:02	9.91	0.002	미만
2014. 05. 28.					
측정위치		측정시간(분)	유량(l/min)	측정농도 [기준: 0.01개/cm ³]	초과 여부
*1	부지경계선1	10:00 ~ 14:10	9.81	불검출 [검출한계 0.002미만]	미만
*2	부지경계선2	10:02 ~ 14:12	9.71	불검출 [검출한계 0.002미만]	미만
*3	부지경계선3	10:05 ~ 14:15	9.84	불검출 [검출한계 0.002미만]	미만
*4	부지경계선4	10:07 ~ 14:17	9.75	불검출 [검출한계 0.002미만]	미만
*5	작업장주변	10:10 ~ 12:20	9.71	불검출 [검출한계 0.002미만]	미만
*6	위생설비입구	10:14 ~ 10:59	9.88	불검출 [검출한계 0.002미만]	미만
*7	폐기물반출구	11:05 ~ 11:50	9.98	0.002	미만

[별첨3] 측정 사진

2014. 5. 27.			
			
*1. 부지경계선	*2. 부지경계선	*3. 부지경계선	*4. 부지경계선
			-
*5. 작업장주변	*6. 위생설비입구	*7. 음압기	-

2014. 5. 28.



*1. 부지경계선



*2. 부지경계선



*3. 부지경계선



*4. 부지경계선




*5. 작업장주변



*6. 위생설비입구



*7. 폐기물반출구



-