

대한22-544

시군구
제출용

석면비산측정 결과보고서

- 비금주민태양광 석면해체공사 -



(주)대한환경컨설팅
CO.,LTD Daehan Environment Consulting

















[별첨1] 측정 위치도(측정 장소) [2022/09/21]




[별첨2] 측정 결과 [2022/09/21]

[illegible]

[별첨3] 측정 사진 [2022/09/21]

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
부지경계선 1,2				
	10:15	14:25	10:17	14:27
부지경계선 3,4				
	10:20	14:30	10:21	14:31
위생설비입구 /작업장주변				
	10:27	11:12	10:30	12:40
폐기물반출구 1,2				
	10:40	11:25	13:22	14:07

















[별첨1] 측정 위치도(측정 장소) [2022/09/22]



[별첨2] 측정 결과 [2022/09/22]

[illegible]

[별첨3] 측정 사진 [2022/09/22]

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
부지경계선 1,2				
	7:31	11:41	7:34	11:44
부지경계선 3,4				
	7:39	11:49	7:44	11:54
위생설비입구 /작업장주변				
	7:55	8:40	8:11	10:21
폐기물반출구 1,2				
	10:02	10:47	14:00	14:45

























[별첨1] 측정 위치도(측정 장소) [2022/09/23]















[별첨2] 측정 결과 [2022/09/23]


시료 번호	측정 지점	측정 장비 (종류/수량)	유량 (ℓ/분)	측정 일시	측정 결과 (f/cc)	비고	
*1	부지경계선1	지역시료채취펌프 SARA-5100	1	9.96	22/09/23	불검출[검출한계 0.002미만]	-
*2	부지경계선2	지역시료채취펌프 SARA-5100	1	9.69	22/09/23	불검출[검출한계 0.002미만]	-
*3	부지경계선3	지역시료채취펌프 SARA-5100	1	9.85	22/09/23	불검출[검출한계 0.002미만]	-
*4	부지경계선4	지역시료채취펌프 SARA-5100	1	9.74	22/09/23	불검출[검출한계 0.002미만]	-
*5	위생설비입구1	지역시료채취펌프 SARA-5100	1	9.76	22/09/23	불검출[검출한계 0.002미만]	-
*6	작업장주변1	지역시료채취펌프 SARA-5100	1	9.96	22/09/23	불검출[검출한계 0.002미만]	-
*7	폐기물반출구1	지역시료채취펌프 SARA-5100	1	9.71	22/09/23	불검출[검출한계 0.002미만]	-
*8	부지경계선5	지역시료채취펌프 SARA-5100	1	9.72	22/09/23	불검출[검출한계 0.002미만]	-
*9	부지경계선6	지역시료채취펌프 SARA-5100	1	9.98	22/09/23	불검출[검출한계 0.002미만]	-
*10	부지경계선7	지역시료채취펌프 SARA-5100	1	9.97	22/09/23	불검출[검출한계 0.002미만]	-
*11	부지경계선8	지역시료채취펌프 SARA-5100	1	9.95	22/09/23	불검출[검출한계 0.002미만]	-
*12	위생설비입구2	지역시료채취펌프 SARA-5100	1	9.72	22/09/23	불검출[검출한계 0.002미만]	-
*13	작업장주변2	지역시료채취펌프 SARA-5100	1	9.99	22/09/23	불검출[검출한계 0.002미만]	-
*14	작업장주변3	지역시료채취펌프 SARA-5100	1	9.86	22/09/23	불검출[검출한계 0.002미만]	-
*15	폐기물반출구2	지역시료채취펌프 SARA-5100	1	9.99	22/09/23	불검출[검출한계 0.002미만]	-
*16	폐기물반출구3	지역시료채취펌프 SARA-5100	1	9.80	22/09/23	불검출[검출한계 0.002미만]	-
*17	폐기물반출구4	지역시료채취펌프 SARA-5100	1	9.88	22/09/23	불검출[검출한계 0.002미만]	-
-	공시료	-	-	-	-	0개/100개시야	-
-	공시료	-	-	-	-	0개/100개시야	-
비 고							
- 일부 지번은 석면해체 작업시간 동안 시료채취를 실시함							

[별첨3] 측정 사진 [2022/09/23]

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
부지경계선 1,2				
	7:51	9:51	7:53	9:53
부지경계선 3,4				
	7:55	9:55	7:59	9:59
위생설비입구1 /작업장주변1				
	8:04	8:49	8:08	10:18
폐기물반출구1 /부지경계선5				
	8:15	9:00	10:01	14:11
부지경계선 6,7				
	10:09	14:19	10:14	14:24
부지경계선8 /위생설비입구2				
	10:19	14:29	10:20	11:05

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
작업장주변 2,3	 10:22	 12:32	 10:31	 11:16
폐기물반출구 2,3	 10:40	 11:25	 14:14	 14:59
폐기물반출구 4	 15:00	 15:45	 -	 -

























[별 첨 1] 측정 위치도(측정 장소) [2022/09/24]



















[별첨2] 측정 결과 [2022/09/24]

시료 번호	측정 지점	측정 장비 (종류/수량)	유량 (ℓ/분)	측정 일시	측정 결과 (f/cc)	비고	
*1	부지경계선1	지역시료채취펌프 SARA-5100	1	10.00	22/9/24	불검출[검출한계 0.002미만]	
*2	부지경계선2	지역시료채취펌프 SARA-5100	1	9.99	22/9/24	불검출[검출한계 0.002미만]	
*3	부지경계선3	지역시료채취펌프 SARA-5100	1	10.00	22/9/24	불검출[검출한계 0.002미만]	
*4	부지경계선4	지역시료채취펌프 SARA-5100	1	9.98	22/9/24	불검출[검출한계 0.002미만]	
*5	작업장주변1	지역시료채취펌프 SARA-5100	1	9.97	22/9/24	불검출[검출한계 0.002미만]	
*6	폐기물반출구1	지역시료채취펌프 SARA-5100	1	10.00	22/9/24	불검출[검출한계 0.002미만]	
*7	위생설비	지역시료채취펌프 SARA-5100	1	9.99	22/9/24	불검출[검출한계 0.002미만]	
*8	부지경계선5	지역시료채취펌프 SARA-5100	1	9.97	22/9/24	불검출[검출한계 0.002미만]	
*9	부지경계선6	지역시료채취펌프 SARA-5100	1	9.95	22/9/24	불검출[검출한계 0.002미만]	
*10	부지경계선7	지역시료채취펌프 SARA-5100	1	9.99	22/9/24	불검출[검출한계 0.002미만]	
*11	부지경계선8	지역시료채취펌프 SARA-5100	1	10.00	22/9/24	불검출[검출한계 0.002미만]	
*12	작업장주변2	지역시료채취펌프 SARA-5100	1	10.00	22/9/24	불검출[검출한계 0.002미만]	
*13	폐기물반출구2	지역시료채취펌프 SARA-5100	1	10.00	22/9/24	불검출[검출한계 0.002미만]	
*14	부지경계선9	지역시료채취펌프 SARA-5100	1	9.99	22/9/24	불검출[검출한계 0.002미만]	
*15	부지경계선10	지역시료채취펌프 SARA-5100	1	9.94	22/9/24	불검출[검출한계 0.002미만]	
*16	부지경계선11	지역시료채취펌프 SARA-5100	1	9.99	22/9/24	불검출[검출한계 0.002미만]	
*17	부지경계선12	지역시료채취펌프 SARA-5100	1	9.98	22/9/24	불검출[검출한계 0.002미만]	
*18	작업장주변3	지역시료채취펌프 SARA-5100	1	9.97	22/9/24	불검출[검출한계 0.002미만]	
*19	폐기물반출구3	지역시료채취펌프 SARA-5100	1	9.99	22/9/24	불검출[검출한계 0.002미만]	
-	공시료		-	-	-	0개/100개시야	-
-	공시료	-	-	-	-	0개/100개시야	-
비 고							
- 일부 지번은 석면해체 작업시간 동안 시료채취를 실시함							

[별첨3] 측정 사진 [2022/09/24]

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
부지경계선 1,2				
	8:02	9:00	8:07	9:00
부지경계선 3,4				
	8:10	9:01	8:13	9:01
작업장주변 1/폐기물반 출구1				
	8:15	9:01	8:20	9:03
위생설비/부 지경계선5				
	9:00	9:45	10:00	11:20
부지경계선 6,7				
	10:03	11:20	10:15	11:21
부지경계선 8/작업장주 변2				
	10:17	11:21	10:15	11:00

폐기물반출 구2/부지경 계선9				
	10:30	11:15	12:45	14:00
부지경계선 10,11				
	12:47	14:00	12:49	14:02
부지경계선 12/작업장주 변3				
	12:51	14:02	12:53	13:38
폐기물반출 구3				
	13:02	13:47	-	-





















[별첨1] 측정 위치도(측정 장소) [2022/09/25]

비금주민태양광 석면해체공사																					
<table><tr><th>시료번호</th><th>시료지점</th></tr><tr><td>*1,2</td><td>죽림리 12-21</td></tr><tr><td>*3</td><td>죽림리 1281</td></tr><tr><td>*4</td><td>덕산리 1-26</td></tr><tr><td>*5</td><td>덕산리 산 54-4</td></tr><tr><td>*6</td><td>구림리 39-27</td></tr><tr><td>*7</td><td>지당리 335-1</td></tr><tr><td>*8</td><td>가산리 213-53</td></tr><tr><td>*9</td><td>가산리 290-3</td></tr><tr><td colspan="2">구역이 광범위하여 위치도 생략함</td></tr></table>		시료번호	시료지점	*1,2	죽림리 12-21	*3	죽림리 1281	*4	덕산리 1-26	*5	덕산리 산 54-4	*6	구림리 39-27	*7	지당리 335-1	*8	가산리 213-53	*9	가산리 290-3	구역이 광범위하여 위치도 생략함	
시료번호	시료지점																				
*1,2	죽림리 12-21																				
*3	죽림리 1281																				
*4	덕산리 1-26																				
*5	덕산리 산 54-4																				
*6	구림리 39-27																				
*7	지당리 335-1																				
*8	가산리 213-53																				
*9	가산리 290-3																				
구역이 광범위하여 위치도 생략함																					
범례	*NO																				
	시료채취																				

[별첨2] 측정 결과 [2022/09/25]

[illegible]

[별첨3] 측정 사진 [2022/09/25]

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
폐기물보관 1,2				
	7:10	7:55	7:10	7:55
폐기물보관 3,4				
	7:18	8:03	7:30	8:15
폐기물보관 5,6				
	7:35	8:20	7:42	8:27
폐기물보관 7,8				
	7:50	8:35	8:25	9:10
폐기물보관9				
	8:40	9:25	-	-

제2020-120001호

석면조사기관 지정서(변경)

기관명	(주)대한환경컨설팅	
소재지	(58323) 전남 나주시 정보화길 26 (빛가람동) 1동 304호	
대표자성명	남가강	
지정사항	총 대행(지정) 한 계	사업장(0)개소, 근로자(0)명
	관할 지역 대행(지정) 한 계	사업장(0)개소, 근로자(0)명
	대행(지정) 지역	

※ 준수사항

1. 석면조사기관기관은 고용노동부장관 또는 지방노동관서장의 자료제출요구 및 점검에 적극 협조하여야 한다.
2. 석면조사기관기관으로 지정받은 기관은 산업안전보건법령에서 정하는 사항을 준수하여야 한다.

『산업안전보건법』 제38조의2 규장의 의하여 석면조사기관으로 지정합니다.

2020. 1. 2.

광주지방고용노동청장

